

CORRES. CONTROL  
OUTGOING LTR. NO.

DOE ORDER # 4700.1

**05-RF-00270**



DIST.	LTR	ENC
DIETER, T.J.		
FERRERA, D.W.	X	
JINDSAY, D.C.		
LONG, J.		
LYLE, J.L.		
MARTINEZ, L. A.		
PIZZUTO, V.M.		
SHELTON, D.C.		
SPEARS, M.S.		
TUOR, N. R.		

JEAN, C.		
JECK, C.		
ROSS, D.		
FRANCIS, M.		
REIBOTH, C.	X	
BEIS, A.		
GIBBS, F.	X	
HUMSTON, T.		
KNAPP, S.		
AVORATO, K.		
INSINBIGLER, H.		
MYERS, K.		
NESTA, S.	X	X
NORTH, K.		
WAMAN, K.		
LAPPERT, R.		
FRIMROSE, A.		
RICHARDELLA, R.		
SNYDER, D.P.		
SWARTZ, J.M.		
VARD, D.A.		
VIEMELT, K.		
HILLS, S.		
HULER, K.		

March 14, 2005

05-RF-00270

Gary Morgan, Functional Lead  
Cadre Project Management Division  
DOE, RFPO

TRANSMITTAL OF CLOSE OUT REPORT FOR BUILDING – T130G – FEG-006-05

Attached is the Closeout Report for the Type 1 facility Building T130G – Office Trailer. Please note that a copy of the report has been submitted to the CERCLA AR by the Kaiser-Hill RISS project.

Please contact Steve Nesta x6386 with questions or concerns.

*Frank E. Gibbs*  
Frank E. Gibbs  
Deputy Project Manager  
Remediation, Industrial D&D, and Site Services

CORRES. CONTROL	X	X
ADMIN RECD/T130G	X	X
TRAFFIC		
ATS/130		

Attachment:  
As Stated

CLASSIFICATION:		
CNI		
UNCLASSIFIED	X	X
CONFIDENTIAL		
SECRET		


SMN:pvt  
Orig. and 1 cc – Gary Morgan

AUTHORIZED CLASSIFIER	
SIGNATURE:	<i>CJ Freeman</i>
Date:	<i>03/15/05</i>
REPLY TO RFP CC NO.:	

CC:  
Joseph Legare  
Deanna McCranie

ACTION ITEM STATUS:	
<input type="checkbox"/> PARTIAL/OPEN	
<input type="checkbox"/> CLOSED	
LTR APPROVALS:	


ORIG. & TYPIST INITIALS:  
SMN:pvt



<b>Section A. Facility Data</b>	
Facility No.	T130G
Facility Descriptor:	Office Trailer, 15,400 square feet
Project:	RISS – Area 5 D&D
Date of Demolition:	February 24, 2005
Additional Information:	Modular corrugated metal office trailer demolished and disposed of as sanitary waste. <i>(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)</i>


<b>Section B. Final Characterization Data</b>	
Reconnaissance Level Characterization Report <i>(concurrence received)</i>	Reconnaissance Level Characterization Report – Concurrence, Steven H. Gunderson to Joseph A. Legare, dated April 22, 2003.
In-process Characterization	N/A
Pre-Demolition Survey Report <i>(approval received)</i>	N/A
Post-Demolition Survey Report <i>(as necessary)</i>	N/A

<b>Section C. Waste Data (complete categories as appropriate)</b>	
<u>Sanitary Disposal</u>	
Disposal Site:	BFI Foothills Landfill, Golden, Colorado
Waste Volume (m <sup>3</sup> ):	2660 Cubic yards
Waste Weight (tons):	602.94 tons
Additional Information:	Above grade building debris
<u>Hazardous Disposal</u>	
Disposal Site:	Kettleman Hills Facility, Kettleman City, CA or Bethlehem Apparatus Co, Hellertown, PA
Waste Volume (m <sup>3</sup> ):	Minor amounts
Additional Information:	Electronic circuit boards, thermostats, exit signs, batteries, fluorescent light bulbs and any other RCRA hazardous components were removed and taken to the RFCA temporary unit for combination with like waste streams for disposal.
<u>TSCA Waste Disposal</u>	
Disposal Site:	
Waste Volume (m <sup>3</sup> ):	N/A
Additional Information:	
<u>Asbestos Waste Disposal</u>	
Disposal Site:	
Waste Volume (m <sup>3</sup> ):	N/A
Additional Information:	
<u>Low-Level Waste Disposal</u>	
Disposal Site:	
Waste Volume (m <sup>3</sup> ):	N/A
Additional Information:	
<u>Low-Level Mixed Waste Disposal</u>	
Disposal Site:	
Waste Volume (m <sup>3</sup> ):	N/A
Additional Information:	
<u>Recycled Material</u>	
Recycle Facility:	
Waste Volume (m <sup>3</sup> ):	
Additional Information:	



# Type 1 Facility Closeout Report

<b>Property Disposition</b>	
Receiver Locations ( <i>major items only</i> ):	N/A
Volume (m <sup>3</sup> ):	
Weight (tons):	
Additional Information:	

<b>Section D. Approvals</b>		
Kaiser-Hill Project Manager	CJ Freeman 	05/10/05
	Name/Signature	Date

## Additional Facility Information

Building T130G was an approximately 15,400 square foot modular trailer acquired in 1991. The structure was corrugated metal siding with corrugated metal skirting. The entrances had wooden stairs leading to a wooden enclosure.


Building T130G had the following utilities: electrical, plant water, plant sanitary and fire protection provided by an overhead sprinkler system and wall mounted fire extinguishers.

The entire T130G structure was removed during D&D activities, and sent offsite for disposal. The utilities were disconnected and removed to at least three feet below final grade as indicated on the attached map. There are no remaining structural components, utility lines, or parts of the foundation. The buildings are not in an IHSS or PAC therefore no soil sampling is required.

### T130G Location Map

#### Map Features

-  Buildings Remaining
-  D&D Facility
-  Paved Roads
-  Dirt Roads
-  Lakes
-  Railroad Removed
-  Railroad Remaining
-  Fence Removed
-  Fence Remaining
-  Streams



1:106  
1 inch equals 15 feet

State Plane Coordinate Projection  
Colorado Central Zone (8478)  
Datum: NAD27

U.S. Department of Energy  
Rocky Flats Environmental Technology Site


Prepared by: GIS Dept. (303) 966-7707





3AD LAYOUT DETAIL  
DRAWING 38975-301

MV 90 EPR CABLE IN  
4" PVC



**ELECTRICAL SITE PLAN**

ETA